

ROOF AREAS

ROOF LABEL	SQUARE FEET	ROOF TYPE	SF OF ROOF DAMAGED/DISPLACED	% OF ROOF DAMAGED/DISPLACED	SF OF ROOF IR MOISTURE SIGNALS	% OF ROOF IR MOISTURE SIGNALS
ROOF AREA # 1	42,100	EPDM	18300	43.5 %	1475	3.5 %
ROOF AREA # 2	8300	EPDM	1600	19.2 %	200	2.5 %
ROOF AREA # 3	6060	EPDM	1470	24.5 %	315	5.2 %
ROOF AREA # 4	3400	EPDM	285	8.3 %	0	N/A
ROOF AREA # 5	475	EPDM	0	N/A	0	N/A
ROOF AREA # 6	4350	SHINGLES	0	N/A	0	N/A
AREA TOTAL	62,450					

LEGEND

SYMBOL	DESCRIPTION
	ROOF DRAIN
	ROOF HATCH
	FIXED LADDER
	VENT PIPE
	GUTTER WITH DOWNSPOUT
	PIPE PENETRATION
	RAISED PIPING
	EXHAUST FAN
	ROOF TOP UNIT
	PITCH POCKET
	UNIT ON SLEEPERS
	DAMAGED/DISPLACED ROOF
	IR MOISTURE SIGNALS



75 HOOD PARK DR.
CHARLESTOWN, MA 02129
P: (617) 268-8977
www.socotec.us

**SOUTHBOROUGH
SCHOOL
DISTRICT**
53 PARKVILLE ROAD,
SOUTHBOROUGH,
MASSACHUSETTS,
01772

Project Title
**ROOF
ASSESSMENT
REPORT**
MARGARET A. NEARY
ELEMENTARY
SCHOOL
53 PARKVILLE RD,
SOUTHBOROUGH, MA, 01772

Project Number AE258241

No.	Description	Date

Stamp

Drawing Title

**DAMAGED ROOF
ASSEMBLY PLAN**

Submission
**ROOF INVESTIGATION
REPORT**

Date JANUARY 23, 2026

Scale AS NOTED

Drawn By MTM Checked By ANB

Drawing Number

A104



1 ROOF AREA PLAN
Scale: 1/16" = 1-0'

