


Article 3 Atwood Water Tank Site Remediation

Background



- Town owned site on Atwood Road
- The site held a water tower from the 1930's to the 1990's
- The tank was “felled” in the 1990's
- Common practice to use lead-based paints on the exterior of the tank.
- There is significant lead contamination in the area of the “drip line” of the tank
- The contamination appears to be stable but we need a long-term solution



- The site has been studied and soil samples taken and assessed.
- Red areas indicate areas of contamination that require addressing.
- Most of the contamination is 12 inches or more below current grade.

What we are asking for:

- \$15,000 for temporary covering of the contaminated areas.
- \$85,000 to develop remediation options, risk assessments, and bid documents.
- Funding for the actual remediation will likely be on the 2026 ATM agenda